

Approved For Release 2002/08/12 : CIA-RDP74B00776R000100080088-6

MFG. 9-66

DATE

SECRET

ROUTING	
1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

TO :

FROM :

ACTION:

INFO :

*FILE*  
*C-167C*

*MD-2-9-12*

IN 73082

*OPG 1-10*

TO

SECRET 170437Z CITE

INFO

CITE

INFO

IDEALIST

REF:

1. TRACKER MALFUNCTION OF TRACKER 306 WHILE ON MISSION C-167C WAS CAUSED BY EITHER STICKING CONTACTS OR RELAY R-3, OR MATERIAL STICKING DUE TO THE TWO HOUR DELAY IN APPLYING POWER TO THE TRACKER ON MISSION C-167C.

2. AFTER MISSION C-167C, RELAY K-3 REPLACED AND TWO MISSIONS WERE SUCCESSFULLY FLOWN. HOWEVER, ON THESE MISSIONS THERE WAS NO DELAY IN APPLYING POWER TO THE TRACKER.

SECRET TOR 171122Z MAY 67

SECRET

Approved For Release 2002/08/12 : CIA-RDP74B00776R000100080088-6

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.

GROUP 1  
EXCLUDED FROM AUTO-  
MATIC DOWNGRADING